

Mehes

Assembly rectangle tables



1



2



3



4



5



6



7



8



9



10



11



click

12



13



Torx 20

14



don't fully fasten the screw

15



4X

16



17



18



4X slide

19



Torx 20

4X fix screws

20



21



22